



Navin Fluorine International Ltd.
Incident Detail Report

Report Date : 26-Aug-2020 16:47

Page No. : 1 of 5

Incident Investigation Basic Detail

Report No :	NFIL/INC/2020/0023	Event Date & Time :	24-Aug-2020 15:10
Department :	HR & FMS	Contractor :	Shilpa hospitality
Plant/Areas : Admin Building		Exact Location :	N/A
Category :	Incident	Report Date & Time :	24-Aug-2020 15:35
Sub Category :	First Aid Case	Shift :	General
Incident At :	On Site	Damage to Asset/Property :	No
Total No. of Persons Affected :	1		
Equipment Involved :	N/A		
Material Involved :	N/A		
Description of what happened :	While working in pantry, suddenly luminary frame fallen; supported with		
Immediate Action Taken (Also mention who visited site first and what action was proposed by him? if applicable) :	N/A		

Investigation Detail

Sequential occurrence :	N/A
Activity of the person(s) /injured at the time of the incident :	N/A
Describe activity happened in incident :	N/A
Observations and inferences (Plant evidences, operating practices, injured person	N/A



Navin Fluorine International Ltd. Incident Detail Report

Report Date : 26-Aug-2020 16:47

Page No. : 2 of 5

experience and relevant training for the work performed etc. which may be cause indicative or helpful to conclude sequence occurrence/cause of the incident): :

Employee(s) / Contractor(s) Injured Details

Employee(s) / Other	Employee Code	Name	Age	Function	Gender
Employee	17970	Sandeep Gajanan Bendre	38	C&I	Male

Property Damage Details

Name of Property/Material :	N/A
Quantity :	N/A
Environment Impact :	N/A
Recovered/Recycled :	N/A
Details of damage to Equipment / Building :	N/A

Injured Person Details

Injured Person 1

Name :	Sandeep Gajanan Bendre	Category Name :	N/A
--------	------------------------	-----------------	-----

Personal Details

Marital Status :	N/A	Contact # :	8550991198
Gender :	Male	Nationality :	N/A
Date of Birth (Age) :	19-Jul-1980 (38 Yrs.)	Employee(s)/Other :	Employee

Injury Details

Nature of Injury :	N/A
Body Part :	N/A
Injuries to internal organ :	N/A
Activity Before Injury :	N/A
Description Of Injury :	N/A
Treatment Given :	N/A
Hospital Or Doctor Name :	N/A
Result of Incident :	N/A



Injured Person Attachment(s)

Sr. #	File Name(s)
No Records Found	

Statement Details

Type	Name	Position	Contact	Statement
No Records Found				

Incident Cause

Direct Causes

A) UNSAFE ACTS :



Navin Fluorine International Ltd. Incident Detail Report

Report Date : 26-Aug-2020 16:47

Page No. : 4 of 5

Tools or Equipment :	N/A	Noncompliance to proper procedures :	N/A		
Protective Methods :	N/A	Distraction / Inattention :	N/A		
B) UNSAFE CONDITIONS :					
Protective Systems :	N/A	Tools, Equipment & Vehicles :	N/A		
Exposures to :	N/A	Work Place Environment :	N/A		
Root Causes					
A) JOB FACTORS :					
Work Planning :	N/A	Tools & Equipment :	N/A		
Communication :	N/A	Supervision :	N/A		
Management :	N/A	Training / Knowledge transfer :	N/A		
Communication() :	N/A				
B) PERSONAL FACTORS :					
People – Physical Wellbeing :	N/A	People – Mental Wellbeing :	N/A		
People – Skill Level :	N/A	People – Behaviors :	N/A		
Reason of Failure :	N/A				
Investigation Team					
Sr. #	Name	Plant	Function	Position	
1	Rajiv Shukla	SURAT	Chemistry	Sr. Officer	
2	Aditya Jain	SURAT	Boiler Maintenance	Associate Manager	
3	Rajesh Kumar Pradhan	SURAT	CNC	Manager	
Recommendation(s)					
Sr. #	Action to be Taken	Responsibility	Priority	Target Date	Status



Navin Fluorine International Ltd. Incident Detail Report

Report Date : 26-Aug-2020 16:47

Page No. : 5 of 5

Recommendation(s)

No Records Found

Comment(s) & Status History

IIR sent for further investigation

By Ravi Patel on 24-Aug-2020 16:09 (Hrs.)

IIR sent for further review

By Ravikumar Reddy on 24-Aug-2020 15:52 (Hrs.)

IIR reported and send for HOD review

By Aditya Jain on 24-Aug-2020 15:35 (Hrs.)

Attachment(s)

Sr. #

File Name(s)

No Records Found