VEHICLE INSPECTION REPORT

Kalye Auto Inspection Center
Report No.: KAI-2024-1187
Petsa ng inspection: September 3, 2024
Inspector: Engr. Rodel P. Santos

Make: Honda
Model/Series: City 1.5 VX CVT
Year Model: 2020
Color: Platinum White Pearl
Plate No.: ABC 5678
Engine No.: L15Z4793370
Chassis No. / VIN: MRHGM6GGXULEUZ7E2
Odometer: 48,215 km

CHECKLIST
Makina ..... OK, walang leak
Transmission ..... OK, smooth ang shifting
Preno (brakes) ..... OK
Ilaw at electrical ..... May sira (tingnan sa notes)
Gulong (tires) ..... Kailangan palitan
Senyales ng baha (flood) ..... Wala

NOTES NG INSPECTOR
- Hindi gumagana ang kaliwang fog lamp, kailangang palitan ang bulb.
- Ang apat na gulong ay 2019 pa ang manufacture date, medyo pudpod na. Estimate ng palit: PHP 18,000.
- May maliit na gasgas sa rear bumper, pang-touch up lang.
- Kumpleto ang service records sa casa hanggang 40,000 km PMS.

Overall rating: 8 / 10
Rekomendasyon: Pwede nang ibenta pagkatapos palitan ang gulong at fog lamp bulb.

SAMPLE DOCUMENT - FICTIONAL DATA FOR SOFTWARE TESTING ONLY