VEHICLE INSPECTION REPORT

Kalye Auto Inspection Center
Report No.: KAI-2024-1302
Petsa ng inspection: October 1, 2024
Inspector: Engr. Rodel P. Santos

Make: Suzuki
Model/Series: Ertiga GL 1.5 AT
Year Model: 2022
Color: Magma Gray
Plate No.: PQR 2468
Engine No.: K15B226574
Chassis No. / VIN: MA3BNC32YJXYP57WD
Odometer: 21,440 km

CHECKLIST
Makina ..... OK, walang leak
Transmission ..... OK, smooth ang shifting
Preno (brakes) ..... OK
Ilaw at electrical ..... May sira (tingnan sa notes)
Gulong (tires) ..... Kailangan palitan
Senyales ng baha (flood) ..... Wala

NOTES NG INSPECTOR
- Mahina ang aircon sa likod (rear AC), kailangang i-check ang blower motor.
- Medyo kalbo na ang dalawang gulong sa harap. Estimate: PHP 9,500.
- Walang palatandaan ng baha o aksidente.
- Ang right side mirror ay may crack sa casing.

Overall rating: 7.5 / 10
Rekomendasyon: Ayusin muna ang rear AC at palitan ang front tires bago i-list.

SAMPLE DOCUMENT - FICTIONAL DATA FOR SOFTWARE TESTING ONLY