



# NCT Report: PASS ADVISORY

Visit [www.ncts.ie](http://www.ncts.ie) to book your full test or retest online and select a date and time that suits you.

## Vehicle/Owner Details

Test Started On: 12-Feb-2026 08:09:34

Owner: CALUM HEALY  
Registration: 10LK601  
Vin: WVVZZZ3CZAE084948  
Manufacturer: VOLKSWAGEN  
Model: PASSAT

Please Check Dashboard Odometer Reading! →  
Any corrections must be notified immediately to a member of staff before leaving the centre, as the recorded mileage cannot be changed afterwards.

Odometer: 242,014km Date 12-02-2026  
Item Modification Report Date

OBD Odometer:

OBD Vin:

## Test Readings

Steering Alignment (m/Km)		Failing Limits	Result
Front Axle	0.0 m/Km	Outside +14 to -14(m/km)	PASS
Rear Axle	-6.0 m/Km	Outside +18 to -18(m/km)	PASS

Suspension	Nearside	Offside	Imbalance	Failing Limits	Result
Front Axle	44 Mm	54 Mm	19 %	Imbalance Above 30%	PASS
Rear Axle	28 Mm	29 Mm	3 %	Imbalance Above 30%	PASS

Brake	Brake Effort		Ovality		Imbalance	Failing Limits	Result
	Nearside	Offside	Nearside	Offside			
Front Axle	3.640 kN	3.730 kN	8 %	10 %	2 %	Performance less than 55 %	PASS
Rear Axle	1.940 kN	2.060 kN	12 %	12 %	6 %	Front Imbalance Above 30 %	
Service Brake Performance	78 %					Rear Imbalance Above 30 %	
						Ovality Above 90 %	
Car Weight	1,494 Kg						
Parking Brake	1.800 kN	1.830 kN			2 %	Parking Imbalance Above 50 %	PASS
Parking Brake Performance	25 %					Performance less than 16 %	

Smoke	Failing Limits	Result
Limits depend on Year of Manufacture		
Smoke 0.050 /m	Engine/Oil Temperature 88 °C	Turbo 1.50 /m
		PASS

Lights	Nearside	Offside	Result
Dip Beam	PASS	PASS	PASS
Full Beam	N/A	N/A	
Fog Light	N/A	N/A	
Aux. Light	N/A	N/A	

## Visual Defects

Item	Description	Location	Result
Tyre Tread	Depth of Tread Less than 3.00mm Worn	NearsideRear, Inner	ADVISORY

## OBD Faults

Item	Code	Description	Location	Type
------	------	-------------	----------	------