

Test Conditions:  $C_d = 0.9$ , Diameter = 0.009 m, Number of Orifices = 1, Temperature = 280.0 K

