



DEMO — NOT A FINAL REPORT

SEWER INSPECTION REPORT
PSI-DEMO-20260730-001



A clear view of the sewer line.

4827 Sample Grove Lane, Indianapolis, IN 46239

INSPECTION DATE

July 30, 2026

PREPARED FOR

Avery Morgan · Fictional client

INSPECTOR

Jordan Hale · Fictional inspector

PROPERTY TYPE

Single-family home

YEAR BUILT

1964

PARCEL

**DEMO-49-99-00-000-
001.000**

OCCUPANCY

**Fictional demonstration
property**



PSI SEWER INSPECTION

Inspection Summary

OVERALL OBSERVATION

The demonstration line remained passable through the visible reach.

The camera reached the public connection at approximately 96 ft. A localized root intrusion with shallow standing water was documented at one joint; no complete blockage was shown in this fictional example.

96 ft

maximum camera reach

2

documented observations

INSPECTION PATH Exterior cleanout to the public connection	ACCESS POINT Front-yard exterior cleanout	CLEANOUT MATERIAL Schedule 40 PVC
CLEANOUT SIZE 4 in	TRANSITION PVC transitions to vitrified clay at approximately 22 ft	RECORD SOURCE Generated demonstration record
PROPERTY TYPE Single-family home	YEAR BUILT 1964	LOT SIZE 0.28-acre lot

PSI SEWER INSPECTION

Findings & Observations

READING THE FINDINGS

Footage is approximate and measured from the stated access point. Feet and inches are shown as ' and ". Findings describe visible conditions and do not constitute a repair specification.

Cleanout to approx. 22'**Visible PVC reach generally clear; material transition noted**

OBSERVED

The visible PVC segment remained generally clear before transitioning to vitrified clay at approximately 22 ft.

Approx. 48'**Localized root intrusion and shallow water**

OBSERVED

A localized root intrusion and shallow standing water were visible at one joint. The center remained passable, and the camera reached the public connection at approximately 96 ft.



PSI SEWER INSPECTION

Inspection Record



GENERATED CAMERA EVIDENCE · APPROX. 48 FT

Localized root intrusion and shallow water

This generated still illustrates how a visible joint condition may be documented in a PSI report.

Demonstration image only. This is not evidence from an actual property inspection.

CAMERA RUN

Inspected line

Path	Exterior cleanout to the public connection
Maximum footage	96 ft
End point	Public connection reached at approximately 96 ft
Access location	Front-yard exterior cleanout

ACCESS AND PIPE

Observed setup

Access details	Accessible threaded cleanout cap
Cleanout material	Schedule 40 PVC
Cleanout size	4 in
Transition	PVC transitions to vitrified clay at approximately 22 ft

INSPECTION SCOPE

What this covers

- A demonstration of PSI's camera-based visual sewer-line reporting format.
- Illustrative visible conditions and approximate camera footage created solely for this sample.
- Generated site, locate, mapping, property, and sewer-camera images used to demonstrate report presentation.

[Demo property-record link](#)

LIMITATIONS

Using the results

- This is a fictional demonstration and does not document an inspection of a real property.
- All names, property details, footage, findings, credentials, and supporting images in this sample are invented.
- No customer video, property record, or private inspection file is connected to this report.
- The ownership disclosure on the final page is PSI's actual standing disclosure and appears on every completed report.
- A real PSI report is limited to portions of the line visible to and reachable by the camera at the time of inspection.

VERIFIED BY

Jordan Hale · Fictional inspector

Demonstration Inspector

This sample illustrates how visible sewer-line conditions are presented in a completed PSI report. No inspection was performed for this fictional property.

INTERNACHI MEMBER ID
DEMO-NACHI0000000

STANDING
Demonstration profile · no inspection performed

REPORT
PSI-DEMO-20260730-001



PSI SEWER INSPECTION

Supporting Documentation



GENERATED SITE DOCUMENTATION

Exterior cleanout access

Generated exterior view illustrating the cleanout used as the demonstration access point.



GENERATED PROPERTY DOCUMENTATION

Fictional property exterior


Generated exterior image for this demonstration report; no real property is represented.



GENERATED LOCATE DOCUMENTATION

Illustrative locator reading

Generated field image illustrating how a recorded sewer-line location may be documented.



GENERATED MAPPING DOCUMENTATION

Illustrative sewer-line path

Generated map showing a fictional path from the exterior cleanout to the public main.



DEMO — NOT A FINAL REPORT

INSPECTION VIDEO

Video access in a completed report.

A completed PSI report links the inspection image and button below to the customer's sewer-camera recording. This demonstration contains no real inspection video.



[Open PSI website](#)

Demo link only. No customer recording, private file, or inspection media is connected to this sample.

Jordan Hale · Fictional inspector
Demonstration Inspector

(317) 620-3858
precisionsewerinspections.com

PSI and Indiana Drain Company are sister companies under shared ownership. PSI reports the evidence and limitations. Recommendations are available when requested and follow your needs. Any cleaning or additional service requires a separate scope, price, and approval. You may choose any provider; additional service does not determine these findings.