

habitability evidence packet — unit 4B (synthetic)

SYNTHETIC DEMONSTRATION — NOT A REAL TENANT CASE

Generated 2026-01-02T09:30:00Z · 3 media item(s), 3 trusted-timestamped · producer db74-b0d8-9050-cff0

This packet documents habitability conditions. It is evidence, not legal advice, and it does not guarantee admissibility. Integrity is independently checkable against the accompanying **bundle.json** with the **habitable verify** tool. An accessible version of this packet is provided as **packet.html**, alongside this PDF.

What this packet proves — and what it does not

What this packet proves

- Each photo's content has not been altered since it was captured (a SHA-256 content hash that can be re-checked against the file).
- Each item existed no later than the date on its trusted timestamp (an RFC 3161 token over the hash) — an upper bound on when it was created.
- The record of events was not reordered or edited after the fact (an append-only, hash-linked chain of custody).

What this packet does not prove

- Who took a photo, or that it depicts a particular home or unit.
- That the underlying condition was as described — that rests on the tenant's own account, not on the cryptography.
- That a timestamp is the exact moment of capture — it is only an upper bound (the content existed by then).
- Admissibility or any legal outcome. This is documentation, not legal advice.

How to verify: run `habitable verify` against the accompanying bundle.json, or cross-check the hashes and RFC 3161 tokens with standard tools. The accessible reading of this packet is packet.html.

What this packet discloses

- The shared photos in this packet have had location (GPS) removed, so they do not reveal where the tenant lives.


Issue: No heat overnight

Category: heat · Room: bedroom · Severity: urgent · Status: open

Synthetic scenario: the room remained cold while the heater was set to warm.

Timeline

- **observed:** Synthetic thermostat display read 49 F during the night.



Captured 2026-01-02T09:15:00Z · hash 81dc3e113fbab34c... · timestamped

Issue: Recurring ceiling leak and mold-like spotting


Category: moisture · Room: bathroom · Severity: high · Status: open
Synthetic scenario: staining returned after rain and spread across the ceiling.

Timeline

- **observed:** Synthetic tenant observed new staining after rainfall.
- **sent_request:** Synthetic repair request sent to the property manager.
- **follow_up:** Synthetic follow-up recorded after the staining expanded.



Captured 2026-01-02T09:05:00Z · hash 3b8407885635d168... · timestamped



Captured 2026-01-02T09:10:00Z · hash 3ee3f8106e1718fd... · timestamped

Evidence appendix

Each item lists its content hash, trusted-timestamp status, and custody status. These verify independently against bundle.json.

Capture	Content hash (SHA-256)	Timestamp	Authority
cap-d871ce0e4d965b97	3b8407885635d168ac0a676d18c194cd170403f4b559e69df29af8ef02be9ec8	verified	sample-offline-rfc3161
cap-7f59015c8a322b59	3ee3f8106e1718fdc4699c3bfa99ff005446008d54f0a71499c5aeb58dff8103	verified	sample-offline-rfc3161
cap-0c2a8d9326ee98ae	81dc3e113fbab34c8134646e2856cd546d668a6169d958aff5012a1c4e26e95d	verified	sample-offline-rfc3161

Generated sample data only. Not legal advice and not evidence from a real home.