

SMART BATTERY REUSE IDENTIFICATION SYSTEM

Battery Condition Analysis Report

Report ID: RPT-20260509115959 · 09 May 2026, 11:59:59

1. BATTERY DETAILS

Parameter	Value
Battery ID	BAT-001
Measured Voltage	3.70 V
Analysis Date	09 May 2026
Analysis Time	11:59:59
Report ID	RPT-20260509115959

2. IMAGE PREPROCESSING STEPS

#	Processing Step	Status
1	User symptom selection verified	COMPLETED
2	Voltage measurement validated	COMPLETED

3. DEFECT ANALYSIS

Defect Type	Status	Severity	Confidence
Phone shuts off at 20-30% suddenly	DETECTED	Moderate	100%
Takes much longer than usual to reach 100%	DETECTED	Moderate	100%
Label Damage	DETECTED	Low	63%

4. CLASSIFICATION RESULT

Classification Grade	Grade C — Not Fit for Reuse
Recommendation	3 defects detected. Battery rejected due to cumulative degradation.

This report was generated by the Smart Battery Reuse Identification System. Results are based on image analysis and voltage measurements. Final reuse decisions must be confirmed by a qualified engineer.