

SMART BATTERY REUSE IDENTIFICATION SYSTEM

Battery Condition Analysis Report

Report ID: RPT-20260509120045 · 09 May 2026, 12:00:45

1. BATTERY DETAILS

Parameter	Value
Battery ID	BAT-001
Measured Voltage	3.70 V
Analysis Date	09 May 2026
Analysis Time	12:00:45
Report ID	RPT-20260509120045

2. IMAGE PREPROCESSING STEPS

#	Processing Step	Status
1	User symptom selection verified	COMPLETED
2	Voltage measurement validated	COMPLETED

3. DEFECT ANALYSIS

Defect Type	Status	Severity	Confidence
Visible damage to battery wrapping/label	DETECTED	Moderate	100%

4. CLASSIFICATION RESULT

Classification Grade	Grade B — Usable with Caution
Recommendation	Minor defect detected (Visible damage to battery wrapping/label). Battery is usable w

This report was generated by the Smart Battery Reuse Identification System. Results are based on image analysis and voltage measurements. Final reuse decisions must be confirmed by a qualified engineer.