

# SMART BATTERY REUSE IDENTIFICATION SYSTEM

Battery Condition Analysis Report

Report ID: RPT-20260509120115 · 09 May 2026, 12:01:15

## 1. BATTERY DETAILS

| Parameter        | Value              |
|------------------|--------------------|
| Battery ID       | BAT-001            |
| Measured Voltage | 5.00 V             |
| Analysis Date    | 09 May 2026        |
| Analysis Time    | 12:01:15           |
| Report ID        | RPT-20260509120115 |

## 2. IMAGE PREPROCESSING STEPS

| # | Processing Step                 | Status    |
|---|---------------------------------|-----------|
| 1 | User symptom selection verified | COMPLETED |
| 2 | Voltage measurement validated   | COMPLETED |

## 3. DEFECT ANALYSIS

| Defect Type                      | Status   | Severity | Confidence |
|----------------------------------|----------|----------|------------|
| Battery percentage drops quickly | DETECTED | Moderate | 100%       |
| Label Damage                     | DETECTED | Low      | 63%        |

## 4. CLASSIFICATION RESULT

|                      |                                                                                    |
|----------------------|------------------------------------------------------------------------------------|
| Classification Grade | Grade B — Usable with Caution                                                      |
| Recommendation       | Minor defect detected (Battery percentage drops quickly, Label Damage). Battery is |

This report was generated by the Smart Battery Reuse Identification System. Results are based on image analysis and voltage measurements. Final reuse decisions must be confirmed by a qualified engineer.