



Beverage Can Europe and Asia

NCR Number	Department	Crew	Liner Number
5	Despatch	A	W11

Non Conformance :

Defect		Group		Immediate Action Taken	
Compound		Compound Gaps 1			
Identified By		Date Issued		Time	
		2014-12-02			
Shift Manager		Operator		Engineer	
Alan O Neill		Alan O Neill		Alan O Neill	
Time Started	Time In Toolroom		Time Finished	Total Downtime	HFI Numbers

Corrective Action Taken:

55

Reading	Gun 1	Gun 2	Gun 3	Gun 4
	5	5	5	
Result				
			5	5
Reading	Gun 5	Gun 6	Gun 7	Gun 8
Result				
		5		

Long Term Action :

55

Department Head :	Alan O Neill	Date Signed Off :
-------------------	--------------	-------------------

