



## Beverage Can Europe and Asia

NCR Number	Department	Crew	Liner Number
4	Engineering	C	W11

Non Conformance :

Defect		Group	Immediate Action Taken	
Curls		Curls Damaged	111	
Identified By	Date Issued		Time	Persons Alerted
11	2014-12-02			11
Shift Manager	Operator		Engineer	Technician
Alan O Neill	Alan O Neill		Alan O Neill	Alan O Neill
Time Started	Time In Toolroom	Time Finished	Total Downtime	HFI Numbers
				11

Corrective Action Taken:

1

Reading	Gun 1	Gun 2	Gun 3	Gun 4
	11	11	11	11
Result				
	1	1	1	
Reading	Gun 5	Gun 6	Gun 7	Gun 8
	11	11	11	11
Result				
	1	1	1	1

Long Term Action :

111

Department Head :	Alan O Neill	Date Signed Off :	11
-------------------	--------------	-------------------	----

