



Northern Natural Gas
1111 South 103rd Street
Omaha, NE 68124

March 11, 2025

Submitted via ERT Database / CEDRI and Certified Mail

U.S. Environmental Protection Agency, Region 7
Air Branch
Attn: Cassandra Mance
Enforcement and Compliance Assurance Division
11201 Renner Blvd
Lenexa, KS 66219

RE: **Mullinville Compressor Station**
Northern Natural Gas Company
Source ID# 0970010
Notification of Compliance Status Report

Northern Natural Gas Company (Northern) respectfully submits this Notification of Compliance Report (Report) demonstrating compliance with Title 40 of the Code of Federal Regulations (CFR) Part 63 Subpart YYYY (National Emission Standards for Hazardous Air Pollutants for Combustion Turbines) for the Mullinville Compressor Station Emission Unit T-27 (rated at 16,329 HP) located at the Mullinville Compressor Station in Mullinville, Kansas as required by §63.6145. The Mullinville Compressor Station's physical location is 14049 17th Avenue, Mullinville, KS 67109.

Each time a notification of compliance status is required under Subpart YYYY, the owner or operator of such source shall submit the following information under §63.9(h)(2)(i)(A)-(G):

A. *The methods that were used to determine compliance;*

EPA Method 320

B. *The results of any performance tests, opacity or visible emission observations, continuous monitoring system (CMS) performance evaluations, and/or other monitoring procedures or methods that were conducted;*

Compressor Turbine Exhaust Emission Unit	Test Date	HAP Tested	Test Result
T27	January 28, 2025	Formaldehyde	22.96 ppb dry @ 15% O ₂

C. *The methods that will be used for determining continuing compliance, including a description of monitoring and reporting requirements and test methods;*

Northern will conduct annual performance testing of formaldehyde using EPA Method 320 to ensure the level is below 91 ppbvd (parts per billion volume dry) or less at 15-percent O₂, except during turbine startup as defined in § 63.6175.

Northern will continuously monitor the operating limitations as specified in the petition submitted May 24th, 2022 to the Administrator. For Emission Unit T27, Northern

petitioned to monitor the following parameters to ensure that the unit was operating in low premixed (LPM) mode (which is known as SoLoNOx for Solar Turbines):

- Gas Producer Turbine Speed (% NGP)
- Inlet Ambient Temperature

Monitoring of these parameters ensures that the facility is operating in “SoLoNOx” mode (lean premixed combustion technology). SoLoNOx is enabled when the system meets minimum load (%NGP) as a function of inlet ambient temperature, as shown in Appendix 1 of the monitoring petition. For the turbine at Mullinville, the SoLoNOx operates above 90% NGP for inlet ambient temperatures between -30 and 120 degrees F.

During the stack tests for Emission Unit T27, the NGP averaged 103.4% with an inlet ambient temperature between 37.5 and 54.1 degrees F.

Northern will report each deviation in the semiannual compliance report according to the requirements in § 63.6150.

- D. *The type and quantity of hazardous air pollutants emitted by the source (or surrogate pollutants if specified in the relevant standard), reported in units and averaging times and in accordance with the test methods specified in the relevant standard;*

Compressor Turbine Exhaust Emission Unit	HAP	Test Result	Averaging Time
T27	Formaldehyde	22.96 ppb dry @ 15% O2	3 Runs, 60 min. ea.

- E. *If the relevant standard applies to both major and area sources, an analysis demonstrating whether the affected source is a major source (using the emissions data generated for this notification);*

40 CFR Part 63, Subpart YYYYY applies to major sources of HAP emissions only. The Mullinville location is a major source of HAP emissions based on potential to emit calculations for the turbine.

- F. *A description of the air pollution control equipment (or method for each emission point, including each control device (or method) for each hazardous air pollutant and the control efficiency (percent) for each control device (or method); and*

No Control Equipment is used. The turbine, Emission Unit T27, is not equipped with an oxidation catalyst.

- G. *A statement by the owner or operator of the affected existing, new, or reconstructed source as to whether the source has complied with the relevant standard or other requirements.*

Northern has complied with Title 40 of the Code of Federal Regulations (CFR) Part 63 Subpart YYYYY.

Statement by a responsible official with that official's name, title, and signature, certifying the truth, accuracy, and completeness of the content of the report

Please see statement below.

This Report is being submitted before the close of business on March 29, 2025, and is considered timely in accordance with §63.6145.

Should you have any further questions, please call Anne Thompson at (402) 398-7558.

"I certify that the information presented herein is true, accurate, and complete to the best of my knowledge."

Sincerely,

A handwritten signature in black ink, appearing to read "Brian Mundt", with a stylized, cursive script.

Brian Mundt
Vice President - Operations

cc: Logan Jones
Compliance and Enforcement
KDHE – Bureau of Air
1000 SW Jackson, Suite - 310
Topeka, KS 66312-1366

Submitted via certified mail and email