policy | desc | 8 cm rise, 30 cm tread, 0 mm nosing | 6 steps | seed 29, env 32













PASS | case completion 93.8% | falls 0, stalls 2, lateral escapes 0
Representative first-episode trace; source: isaaclab/logs/2026-10-11_01-21-27_easy100-core-checkpoints/result.json
Missing panels mean telemetry was not recorded. Contact-foot speed is a slip proxy; plots alone do not certify smoothness.