hard520 actual failure terminal snapshots | front F1/F2, rear F3/F4
Closed overhang slabs shown physically; endpoints locate stalls without proving collision mechanism.