policy | desc | 16 cm rise, 27 cm tread, 0 mm nosing | 6 steps | seed 29, env 0













FAIL | case completion 100.0% | falls 0, stalls 0, lateral escapes 0
Representative first-episode trace; source: isaaclab/logs/2026-10-11_03-11-42_standard370-16cm-desc-speed03-video/result.json
Missing panels mean telemetry was not recorded. Contact-foot speed is a slip proxy; plots alone do not certify smoothness.