MIL-T-81077A(OS)
Amendment 2
29 April 1969
Superseding
Amendment 1
20 January 1967

MILITARY SPECIFICATION

TEST SET, ELECTRICAL CABLE

MARK 444 MOD 0

(For Torpedo Mk 46 Mods 0 and 1)

This amendment forms a part of Military Specification MIL-T-81077A(OS) dated 10 October 1966 and has been approved by the Naval Ordnance Systems Command, Department of the Navy

Page 8, paragraph 4.5.1. Add after subparagraph (f):
"(g) Insulation test fixture in accordance with Figure 2".

Page 10, paragraph 4.7.3.1(j): Delete "825,00 ohms" and substitute "825,000 ohms".

Page 13, paragraph 4.7.3.1. Add after subparagraph (r):
"(s) Disconnect the checkout cable from connectors J1 and J3.

(t) Connect the insulation test fixture to connector J1 as illustrated in Figure 2.

(u) Rotate test mode switch to auto position. Observe that number 01, illuminated in red, appears on the test number monitor.

(v) Rotate the test circuit switch to position 2. Observe that number 01, illuminated in green, appears on the test number monitor.

(w) Depress advance switch. Observe that number 02, illuminated in red, appears on the test number monitor.

(x) Rotate the test circuit switch, repeatedly, through positions 3 to 52, then to 1 and observe that the test number monitor shall advance one number, illuminated in red, with each switch advance until a "satisfactory end-of-test" has been indicated (see 6.3.5).

(y) Disconnect the insulation test fixture.

FSC 1355

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:58Z
Check the source to verify that this is the current version before use.

(z) Connect the checkout cable to connectors J1 and J3 as illustrated in Figure 1."

Page 13: Add Figure 2 after paragraph 4.7.3.1.

Page iii, APPENDIX, paragraph 10.3.1. Add after subparagraph (p):

"(q)	Test number monitor 01 illuminates in red	4.7.3.1(u)	_____
(r)	Test number monitor 01 illuminates in green	4.7.3.1(v)	_____
(s)	Test number monitor advances to 02, illuminates in red	4.7.3.1(w)	_____
(t)	Test number monitor advances through 52, illuminates in red	4.7.3.1(x)	_____
(u)	Test number monitor advances to "satisfactory-end-of-test"	4.7.3.1(x)	_____ "

Project No. 1355-N046

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:58Z
Check the source to verify that this is the current version before use.




FIGURE 2. INSULATION TEST FIXTURE

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T04:58Z
Check the source to verify that this is the current version before use.