


Event ID:	EVT-3BC2F5E7	Severity Rating:	MEDIUM
Defect Type:	GARBAGE DETECTED	Status:	CONFIRMED
Camera Node:	CAM-01	Video Offset / Frame:	00:10.000 (Frame #240)
Location / Sector:	National Highway NH-44 Sector 2	GPS Coordinates:	28.6139, 77.2090

Forensic AI Description: Roadside garbage / waste debris detected (area: 554 sq px)

Forensic Evidence Snapshot (CCTV Capture)



Target Authority:	Municipal Corporation / PWD Highways & Traffic Safety Cell	Dispatch Priority:	MEDIUM - Immediate Remediation
Recommended Action:	Deploy road maintenance crew, dispatch asphalt patch/drainage unit, update GIS alert index.	Verification:	Automated AI YOLOv8 + OpenCV Seal