

PROFESSIONAL CLEANING EQUIPMENT LTD

Engineer's Job Sheet / Service Report · Reg: 12345678 · Manchester, UK · +44 161 000 0000

- ☐ INSPECTION / FAULT REPORT
- ☒ REPAIR
- ☐ PLANNED SERVICE
- ☐ COMMISSIONING

Job No: CL-2026-0187

Owner / Account: Northern Facilities Ltd

Customer: CityGate Business Centre — Soft Services

Site: Deansgate 120, Manchester M3 2GA (basement plant room)

Asset make / model: Nilfisk SC500 53 B Full TractionHours / meter: 2105

Serial: 908 7341 010 / SN NF-SC500-2024-55102

Labour hours: 2.5

Travel (km): 14

☒ YES☐ NO

Fault reported / customer request:

Poor suction on carpet — machine no longer picks up fine dust. Operators report unusual noise from the cylindrical brush and a burnt-filter smell after ~30 min. Urgent call-out requested before weekend (building occupancy high).

Parts used:

No.	Description	Part No	Qty	Price € ex VAT each
1	HEPA circular filter	6.414-631.0	1	42.00
2	Cylindrical brush standard 53 cm	4.762-450.0	1	78.00
3	Dirty-water tank seal	5.035-488.0	1	14.50
4	Brush drive belt (~€18)	6.666-017.0	1	18.00
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				

Date fault reported
2026-09-18

Customer sign-off
James Hartley (Facilities Supervisor)
Signature / name / company stamp

Engineer sign-off
Tom Bradley
Name / signature

Date of technical intervention
2026-09-19

Work carried out / notes:

Replaced HEPA + brush + belt. Carpet suction test: OK. Operator briefing: empty tank after each shift, check filter weekly. Next service recommended at 2200 hours.

Parts listed above were replaced for the following reasons:

HEPA filter clogged (>90% saturated) — insufficient suction. Brush worn on 40% of length, bristles pulled. Cracked belt — noise and torque loss.

Customer sign-off

Engineer sign-off

James Hartley (Facilities Supervisor)

Tom Bradley