

TRICOLITE

Unit 1 : Plot No. 18/1A, Site IV , Industrial Area
Sahibabad – 201010 ,UP, INDIA.

Unit 2 : Plot No. 5, Sector-VI, IMT Manesar,
Gurgaon, Haryana - 122050, INDIA

Ph : +91-120-4550400,Email: customercare@tricolite.com

CCC/QR/01/00

Report No: : R-54309

Customer : Sterling and Wilson Solar Ltd.

Contact
Person : Mr. Livein,

Mobile No. : 9677714033

Project : 35MW Solar Power Plant, Gujrat

So. Number : SO/1920/AUG/0016

Product
Model : MV - MV-11KVCB18.4

Product : FG24738 11KV Inverter HT Panel-Type-1-
OD-Jaloya-SO/1920/AUG/0016-

Service Detail

Request No. : 54309 (Sale/Warranty)

Request Date : 22 Jan 2020 10:56AM

Nature of
Complaint : Malfunctioning

Service Engineer : Shyamender

Sub. Engineer :

	Date & Time		Date & Time
Call Received	22 Jan 2020 10:56AM	Call Responded	22 Jan 2020 12:27PM
Engineer Reached	22 Jan 2020 12:27PM	Call Completed	23-Jan-2020 12:41 PM

Detail description

KWH Meter changing

Detail of product failure**Work done at site**

1) Visited the site all systems checked and- 1Nos KWH Meter
premier 300(E3M024 3phone 4wire) 2300/1A changing and
Testing done S.N : X1304792 2) PT Fuse Failure Relay problem
Resolve 3) 1 no 2 C/O relay base faulty OMRON block-2 O/G
feeder 1) Visited the site all systems checked and TVM (KWH)
changing and all Reading checked done

Used Material Summary

Material Detail	Material Amount	0.00
	Manpower Cost	0.00

Last Report Sign by

Customer Signature
(Mr. Livein,)

Sign Date : 23 Jan 2020

