



Final Inspection Report

Field	Value
Inspection Date	2221-02-11
Product Category	Home Textile
Supplier Name	1234
Item Description	aade
Design No	443
Colour	green
Checker Name	Aayan
Fabric Quality	idk
Merchandiser Name	idk
Order Quantity	111
Presented Quantity	11
Number of Pieces Inspected	111
Sampling Range Selected	3201-10000
Inline Inspection Performed?	Yes
PP Sample Approved?	Yes
Packing List Available?	Yes
PO Quantity Match?	Yes
Storage OK?	
Total No. of Cartons	124141
Inspected Cartons	1214
Inspection Result	Rework
Final Comments	asdasd

Defects Summary

Defect Type	Minor	Major	Image(s)
1231	01231	022	defect_partner3.png
			

4124	0231	011	defect_partner3.png
			

Inline Pictures



PP Sample Pictures



Packing List Pictures



PO Pictures



Storage Pictures



Carton Pictures



Signatures

QC Officer:

A handwritten signature consisting of a stylized, overlapping 'A' shape followed by a long, sweeping horizontal line extending to the right.

Supplier Representative:

A handwritten signature featuring a series of sharp, vertical strokes followed by a horizontal line and a small upward flick at the end.

Assistant Quality Manager:

A handwritten signature with a series of sharp, vertical strokes followed by a horizontal line and a small upward flick at the end.

Merchandiser:

A handwritten signature consisting of a stylized, overlapping 'A' shape followed by a long, sweeping horizontal line extending to the right.