

DataStream Report

The Report is created by **LAUNCH** X-431

Vehicle Information

Year:2008

Make:GM

Model:Yukon XL

VIN:1GKFK16368J144884

Vehicle Software Version:V50.35

Diagnostic Application Version:V8.00.037

Diagnostic path:Automatically Search > Engine Control Module (ECM)



Repair Shop

Shop Name:BC

Address:

Zip Code:

Telephone:

Email:

SN:989347712041

Test Time:2026-03-14 14:27:46



Data Stream 【Pre-Repair】

Name	Value	Unit
Accelerator Pedal Position (APP) Indicated Angle	0.500	%
Air Conditioning (A/C) Relay Command	Off	
Air Flow Calculated	0.117	g/s
Calculated Three Way Catalyst (TWC) Temperature Bank 1	599	degree F
Calculated Three Way Catalyst (TWC) Temperature Bank 2	599	degree F
Camshaft Position (CMP) Sensor	0	rpm
Cycles Of Misfire Data	86	
Cylinder 1 Injector Circuit Open Test Status	Not Run	
Cylinder 1 Injector Circuit Short Gnd Test Status	Not Run	

Cylinder 1 Injector Circuit Short Volts Test Status	Not Run
Cylinder 1 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 1 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 1 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 2 Injector Circuit Open Test Status	Not Run
Cylinder 2 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 2 Injector Circuit Short Volts Test Status	Not Run
Cylinder 2 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 2 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 2 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 3 Injector Circuit Open Test Status	Not Run
Cylinder 3 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 3 Injector Circuit Short Volts Test Status	Not Run
Cylinder 3 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 3 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 3 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 4 Injector Circuit Open Test Status	Not Run
Cylinder 4 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 4 Injector Circuit Short Volts Test Status	Not Run
Cylinder 4 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 4 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 4 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 5 Injector Circuit Open Test Status	Not Run

Cylinder 5 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 5 Injector Circuit Short Volts Test Status	Not Run
Cylinder 5 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 5 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 5 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 6 Injector Circuit Open Test Status	Not Run
Cylinder 6 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 6 Injector Circuit Short Volts Test Status	Not Run
Cylinder 6 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 6 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 6 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 7 Injector Circuit Open Test Status	Not Run
Cylinder 7 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 7 Injector Circuit Short Volts Test Status	Not Run
Cylinder 7 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 7 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 7 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run
Cylinder 8 Injector Circuit Open Test Status	Not Run
Cylinder 8 Injector Circuit Short Gnd Test Status	Not Run
Cylinder 8 Injector Circuit Short Volts Test Status	Not Run
Cylinder 8 Instrument Cluster (IC) Circuit Open Test Status	Not Run
Cylinder 8 Instrument Cluster (IC) Circuit Short Gnd Test Status	Not Run
Cylinder 8 Instrument Cluster (IC) Circuit Short Volts Test Status	Not Run

Cylinder Deactivation Performance Test	OK	
Engine Coolant Temperature (ECT) Sensor	140	degree F
Engine Load	0	%
Engine Oil Pressure Sensor	3	psi
Engine Run Time	00:00:00	
Engine Speed	0	rpm
Fuel Tank Level Remaining	98.931	%
Ignition 1 Signal	0.024	V
Injector 1 Disabled Due To Misfire	No	
Injector 2 Disabled Due To Misfire	No	
Injector 3 Disabled Due To Misfire	No	
Injector 4 Disabled Due To Misfire	No	
Injector 5 Disabled Due To Misfire	No	
Injector 6 Disabled Due To Misfire	No	
Injector 7 Disabled Due To Misfire	No	
Injector 8 Disabled Due To Misfire	No	
Injector PWM Bank 1	0	ms
Injector PWM Bank 2	0	ms
Intake Air Temperature (IAT) Sensor	57.2	degree F
Malfunction Indicator Lamp (MIL) Requested By DTC	No	
Manifold Absolute Pressure (MAP) Sensor	14.7	psi
Mass Air Flow (MAF) Sensor	0	g/s
Misfire Current Cylinder 1	0	
Misfire Current Cylinder 2	0	
Misfire Current Cylinder 3	0	
Misfire Current Cylinder 4	0	
Misfire Current Cylinder 5	0	
Misfire Current Cylinder 6	0	
Misfire Current Cylinder 7	68	
Misfire Current Cylinder 8	0	
Misfire History Cylinder 1	0	
Misfire History Cylinder 2	24	
Misfire History Cylinder 3	3	

Misfire History Cylinder 4	2	
Misfire History Cylinder 5	0	
Misfire History Cylinder 6	1	
Misfire History Cylinder 7	1028	
Misfire History Cylinder 8	8	
Power Enrichment	Inactive	
Spark	30.500	deg
Throttle Position (TP) Indicated Angle	25.637	%
Total Misfire	64	counts
Vehicle Speed Sensor	0	mph

.....

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!