

DataStream Report

The Report is created by **LAUNCH X-431**

Vehicle Information



Year:2007

Make:VOLVO

Model:S60

VIN:YV1RS592272608372

Engine Size:B5254T2

Odometer:110971 miles

Vehicle Software Version:V44.95

Diagnostic Application Version:V8.00.029

Diagnostic path:Automatically Search > System Selection > ECM (Engine Control Module)

Notes:before microcenter trip

Repair Shop

Shop Name:

Address:

Zip Code:

Telephone:

Email:

SN:989347712041

Test Time:2025-10-20 08:27:53

Notes:before microcenter trip



Data Stream 【Pre-Repair】

Name	Value	Unit
A/C Compressor Active	Off	
A/C Pressure	50.475	psi
Accelerator Pedal Sensor, Analog	0.41	V
Accelerator Pedal Sensor, PWM	8.00	%
Adaptation Throttle	---	
Air Mass, Correction Factor	---	
Ambient Air Pressure	---	hPa
Ambient Air Temperature	---	degree C
Battery Voltage	---	V

Boost Pressure	---	hPa
Brake Light Switch	---	
Brake Pedal Position (From BCM)	---	%
Camshaft Shifting Angle Deviation (Exhaust)	---	deg
Camshaft Shifting Angle Deviation (Inlet)	---	deg
Camshaft Shifting Angle, Exhaust	---	deg
Camshaft Shifting Angle, Inlet	---	deg
Condition Automatic Transmission	---	
Cruise -	---	
Cruise +	Off	
Cruise Control Resume	Off	
Engine Coolant Level Switch	Off	
Engine Coolant Temperature	189.95	degree F
Engine Cooling Fan	7.84	%
Evap-Flow	0.51	kg/h
Exhaust Camshaft Adaptation	2.37	deg
Exhaust Camshaft Reset Valve	40.39	%
Fuel Pressure	60.362	psi
Fuel Pressure, Nominal Value	60	psi
Fuel Pump Relay	On	
Fuel Pump, Duty Cycle	45.92	%
Fuel Temperature	87.8	degree F
Idlespeed, Deviation From Nominal	0	rpm
Ignition Angle	12.00	deg BTDC
Injection Time, Bank 1	1.61	ms
Inlet Camshaft Adaptation (6-Cyl)	-1.19	deg
Inlet Camshaft Reset Valve	7.84	%
Intake Air Temperature	57.65	degree F
Lambda Control, Bank 1	C/L	
Leakage Air Through Throttle Blade	0	
Long-Term Fuel Trim Lower Part Load, Bank 1	1.04	
Long-Term Fuel Trim Upper Part Load, Bank 1	1.00	

Mass Air Flow	9	kg/h
Misfire Counter	0	
Misfire Counter 1 (5 Cyl)	0	
Misfire Counter 2 (5 Cyl)	0	
Misfire Counter 3 (5 Cyl)	0	
Misfire Counter 4 (5 Cyl)	0	
Misfire Counter 5 (5 Cyl)	0	
Nominal Camshaft Shifting Angle, Exhaust	9	deg
Nominal Camshaft Shifting Angle, Inlet	0	deg
Nominal Throttle Angle	1.57	%
Oil Level	79.68	%
Oil Pressure Switch	Off	
Oxygen Front Sensor, Bank 1	1.02	
Oxygen Rear Sensor, Bank 1	0.73	V
Purge Valve, Dutycycle	16.01	%
Short-Term Fuel Trim Idle, Bank 1	3.61	%
Short-Term Fuel Trim, Bank 1	1.01	
Throttle Angle	1.57	%
Throttle Position Sensor, Potentiometer 1	0.63	V
Throttle Position Sensor, Potentiometer 1	1.57	%
Throttle Position Sensor, Potentiometer 2	4.37	V
Throttle Position Sensor, Potentiometer 2	1.57	%
Turbo Control Valve Dutycycle	0	%
Vehicle Speed	0	mph

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!