

Cascade Commons — Demonstration Document — Fictional

Fictional fire protection contractor, licensed for demonstration purposes only

Fire Protection Inspection Report — Annual

Property: Cascade Commons · 4820 Cascade Parkway, Austin, TX 78745 · Parcel TRAVIS-02-4417-0209

Inspection date	October 20, 2025
Systems	Wet-pipe automatic sprinkler (one riser), monitored fire alarm, exit and emergency lighting
Result	PASS — tags applied
Deficiencies corrected	Two corroded sprinkler heads in the loading corridor replaced same day
Main drain test	Static 68 psi / residual 54 psi — within range
Alarm transmission	Verified with the monitoring station
Next annual inspection due	October 20, 2026

Inspector

Property manager

Date

Cascade Commons — Demonstration Document — Fictional. This document was generated for a product demonstration. The property, owner, manager, lender, contractors, amounts, account numbers and signatures are invented; any resemblance to a real person, company, parcel or account is coincidental. It is not a bill, a policy, a contract or a public record.