

VEHICLE INSPECTION & INDEMNITY

Platform Admin

Customer: Ryan Meyer

Reg: TE 11 ST GP

Vehicle: VW Golf GTI

Date: Tue, 03 Mar 2026 15:52

Template Version: 1

Booking Ref: #07EEBD26

Location at Signing: -26.532727, 28.062989

Inspection: Before Service (Arrival)



Inspection: After Service (Completion)



Authorization & Acceptance

By signing below, the customer acknowledges the pre-existing condition of the vehicle as documented in the "Before" photos and accepts the terms of the indemnity agreement.

Henlo

Customer Signature

Verification Details:

Digital Signature Hash: c8fc8b75cb50114e082eaff88b020bcf556a987e87865ba05ccbe31f17bee9cb

Signed at: Ewelme Road, Henley on Klip, Midvaal Ward 4, Midvaal Local Municipality, Sedibeng District Municipality, Gauteng, 1960, South Africa

Coordinates: -26.532727, 28.062989

■ [View on Google Maps](#)