

VEHICLE INSPECTION & INDEMNITY

CBA

Customer: CBA Customer 1 csm

Reg: TE 11 ST GP

Vehicle: VW Golf GTI

Date: Wed, 04 Mar 2026 16:23

Template Version: 4

Booking Ref: #42A96C1C

Location at Signing: -26.532727, 28.062989

Inspection: Before Service (Arrival)



Inspection: After Service (Completion)



Authorization & Acceptance

By signing below, the customer acknowledges the pre-existing condition of the vehicle as documented in the "Before" photos and accepts the terms of the indemnity agreement.

A handwritten signature in black ink, consisting of a series of loops and a final horizontal stroke.

Customer Signature

Verification Details:

Digital Signature Hash: 5fad33149a6c1f3e4049fbd03af47b6939b2437b3a95558a124b5acf30479e13

Signed at: Ewelme Road, Henley on Klip, Midvaal Ward 4, Midvaal Local Municipality, Sedibeng District Municipality, Gauteng, 1960, South Africa

Coordinates: -26.532727, 28.062989

■ [View on Google Maps](#)