

VEHICLE INSPECTION & INDEMNITY

CBA

Customer: CBA Customer 1 csm

Reg: TE 11 ST GP

Vehicle: VW Golf GTI

Date: Wed, 04 Mar 2026 16:24

Template Version: 4

Booking Ref: #9813DC0D

Location at Signing: -26.532718, 28.062988

Inspection: Before Service (Arrival)



Inspection: After Service (Completion)



Authorization & Acceptance

By signing below, the customer acknowledges the pre-existing condition of the vehicle as documented in the "Before" photos and accepts the terms of the indemnity agreement.

A handwritten signature in black ink, appearing to be 'S' followed by a long horizontal stroke.

Customer Signature

Verification Details:

Digital Signature Hash: 7f5dc9553c9ba01fe7acd608e3f5814d2744eaefb59478f391595a634d863f56

Signed at: Ewelme Road, Henley on Klip, Midvaal Ward 4, Midvaal Local Municipality, Sedibeng District Municipality, Gauteng, 1960, South Africa

Coordinates: -26.532718, 28.062988

■ [View on Google Maps](#)