

Maintenance Work Order: WO-2024-0892

Work Order ID: WO-2024-0892

Status: Completed

Date: March 12, 2024

Technician: Rajesh Kumar

Asset Tag: P-101A (Primary Feed Pump Unit-4)

Location: Unit-4 Refinery Pump House

Description: Preventive maintenance and clearance checks.

Findings:

During inspection, technician Rajesh Kumar checked the pump P-101A bearing wear.

The shaft clearance was measured at 0.8mm which exceeds the design tolerance limit of 0.3mm.

Recommended replacement of the inboard bearings during next scheduled shutdown.

Action Taken:

Lubricant replaced and bearings greased. Shaft realigned. Pump restarted and vibration checked within acceptable range.

Signed: Rajesh Kumar