

Routine inspection - P-1101 (2025-12-02)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	P-1101
Name	Distillate transfer pump
Class	CP100
Plant / Unit / Area	MV / U100 / Solvent Transfer
Service duty	Light solvent transfer, ambient
Criticality	C
Installed on	2018-11-10

2. Summary

General condition inspection completed. Readings within normal limits; housekeeping and external condition acceptable. Continue normal monitoring.