

Routine inspection - P-1102 (2022-11-01)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	P-1102
Name	Reflux pump
Class	CP100
Plant / Unit / Area	MV / U100 / Distillation
Service duty	Reflux return, 60 C
Criticality	B
Installed on	2018-11-10

2. Summary

Scheduled inspection performed. No leaks, abnormal noise or vibration observed. Equipment fit for continued service.