

Routine inspection - M-3401 (2021-03-19)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	M-3401
Name	Motor for P-3401
Class	MOT
Plant / Unit / Area	MT / U300 / Esterification
Service duty	Drives ester feed pump A
Criticality	A
Installed on	2019-05-14

2. Summary

General condition inspection completed. Readings within normal limits; housekeeping and external condition acceptable. Continue normal monitoring.