

Routine inspection - M-3105 (2024-09-03)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	M-3105
Name	Motor for P-3105
Class	MOT
Plant / Unit / Area	MV / U100 / Distillation
Service duty	Drives solvent bottoms pump
Criticality	A
Installed on	2020-02-20

2. Summary

General condition inspection completed. Readings within normal limits; housekeeping and external condition acceptable. Continue normal monitoring.