

Routine inspection - M-2210 (2025-03-09)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	M-2210
Name	Motor for P-2210
Class	MOT
Plant / Unit / Area	MV / U200 / Blending
Service duty	Drives resin transfer pump
Criticality	B
Installed on	2020-08-03

2. Summary

Routine inspection carried out. Equipment found in satisfactory operating condition with no abnormality requiring corrective action at this time.