

Routine inspection - M-1101 (2023-11-09)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	M-1101
Name	Motor for P-1101
Class	MOT
Plant / Unit / Area	MV / U100 / Solvent Transfer
Service duty	Drives distillate transfer pump
Criticality	C
Installed on	2018-11-10

2. Summary

Scheduled inspection performed. No leaks, abnormal noise or vibration observed. Equipment fit for continued service.