

Routine inspection - M-3301 (2023-10-15)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	M-3301
Name	Motor for filtrate pump
Class	MOT
Plant / Unit / Area	MT / U300 / Filtration
Service duty	Drives filtrate pump
Criticality	C
Installed on	2020-06-15

2. Summary

General condition inspection completed. Readings within normal limits; housekeeping and external condition acceptable. Continue normal monitoring.