

Routine inspection - M-4101 (2025-02-03)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	M-4101
Name	Motor for cooling water pump
Class	MOT
Plant / Unit / Area	MT / U400 / Cooling Water
Service duty	Drives cooling water pump
Criticality	B
Installed on	2017-09-01

2. Summary

Scheduled inspection performed. No leaks, abnormal noise or vibration observed. Equipment fit for continued service.