

Routine inspection - E-4110 (2023-10-05)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	E-4110
Name	Cooling water plate cooler
Class	HEX
Plant / Unit / Area	MT / U400 / Cooling Water
Service duty	Closed-loop cooling
Criticality	C
Installed on	2017-09-01

2. Summary

Scheduled inspection performed. No leaks, abnormal noise or vibration observed. Equipment fit for continued service.