

Routine inspection - A-3120 (2024-11-02)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	A-3120
Name	Blend vessel agitator
Class	AGI
Plant / Unit / Area	MT / U300 / Product Transfer
Service duty	Product blend mixing
Criticality	C
Installed on	2020-03-11

2. Summary

General condition inspection completed. Readings within normal limits; housekeeping and external condition acceptable. Continue normal monitoring.