

Routine inspection - C-4110 (2023-12-07)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	C-4110
Name	Plant air compressor 1
Class	COMP
Plant / Unit / Area	MT / U400 / Cooling Water
Service duty	Plant air supply
Criticality	B
Installed on	2017-09-01

2. Summary

Scheduled inspection performed. No leaks, abnormal noise or vibration observed. Equipment fit for continued service.