

Routine inspection - C-4120 (2021-03-20)

Inspection Report | Tier 3

1. Asset

Field	Value
Asset tag	C-4120
Name	Plant air compressor 2
Class	COMP
Plant / Unit / Area	MT / U400 / Cooling Water
Service duty	Plant air supply (standby)
Criticality	C
Installed on	2017-09-01

2. Summary

Scheduled inspection performed. No leaks, abnormal noise or vibration observed. Equipment fit for continued service.