

Annual condition inspection (P-3401)

Inspection Report | Tier 1

1. Asset

Field	Value
Asset tag	P-3401
Name	Ester feed pump A
Class	CP200
Plant / Unit / Area	MT / U300 / Esterification
Service duty	Hot organics transfer - molten ester feed, 185 C
Criticality	A
Installed on	2019-05-14

2. Findings

Routine annual inspection of P-3401. Vibration and bearing temperatures within limits. Seal flush flow adequate at time of check. General condition satisfactory; continue monitoring flush arrangement.

3. Recommendation

Verify the seal flush plan on this and the sister CP200 pumps against the OEM MSC-CP200 manual (API Plan 11) and correct any field deviation before further seal replacement.