

## Disconnected piezo test

---

Disconnected piezo

### Piezo information

Paddock section: RDS


Piezometer ID: VW-29

Inspection date: 2023-03-10

Average PWP (From 2023-02-07 09:00:00 to 2023-02-15 09:00:00):

475.371 KPa

## Latest piezometer lectures ( last 100 days )



# Section graph

