AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 09 Apr 2026 | Lot size: 11,925 m² | Confidence: High

Executive Summary

A current pond feature is present on-site. Adjacent off-site water features were identified and treated as contextual only.

Assessment Boundary

Current north-up image showing the drawn lot assessment boundary used for this screening.

Key Flags

Former Water Features	**Elevated**
A current pond feature is present on-site.	
Fill / Disturbance	**Low**

No clear on-site disturbance or fill-related ground modification was carried through the final interpretation.

Recommendation

A current on-site water feature is present and should be considered in geotechnical assessment. Detailed geotechnical investigation is strongly recommended.

Current Site Image

North-up current imagery. Polygon shown for site reference. Any visible disturbance is highlighted only if clear.

Source: mapbox_bbox_site

Geotechnical Risk Summary

The following preliminary risk commentary is based on the interpreted site history features identified from available aerial imagery.

Pond / Wet Area Risk — HIGH

The presence of a current pond or pond-like depression within the site indicates localised moisture influence and potential variability in subsurface conditions. Such features are commonly associated with elevated moisture contents, soft or compressible soils, and conditions that may contribute to ground movement. These areas may remain seasonally wet or act as surface water collection points, which can impact foundation performance and are relevant to site classification considerations in accordance with AS2870.

Historical Evidence

Best historical image showing the clearest former water feature evidence.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | 1995-06-18

Later Comparison Image

Later imagery used to check whether the historical water feature remains visible or appears altered.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | 2021-07-17

Limitations & Disclaimer

- Imagery resolution limits small-scale disturbance detection.
- No recent underground or subsurface data available.
- Imagery interpretation remains preliminary and should be manually reviewed where uncertainty persists.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.