AI SITE HISTORY REPORT

Address	502 Church Road, Taigum QLD
Generated	16 Apr 2026
Lot size	11,925 m^2
Years scanned	1995, 2005, 2011, 2015, 2019, 2021
Confidence	High

Preliminary Screening Notice

This report is generated using automated interpretation of available aerial imagery and is intended for preliminary site screening purposes only.

While reasonable effort has been made to identify visible indicators such as ponds, historical water features, and site disturbance, not all features may be detected or accurately interpreted.

Users are strongly encouraged to independently review historical imagery (e.g. Google Earth) and obtain a detailed geotechnical investigation in accordance with AS2870 prior to design, construction, or purchase decisions.

Current Site Overview

Figure 1: Current site overview used for automated screening.

Executive Summary

A current pond feature is present on-site. Site disturbance or possible fill-related ground modification is also visible. Adjacent off-site water features were identified and treated as contextual only.

Key Site Risks

Current Pond / Wet Area	High
A current pond or pond-like depression is present on-site and should be treated as a relevant moisture-related geotechnical risk.	
Former Water Features	Elevated
A current pond feature is present on-site.	
Fill / Disturbance	Elevated
Recent on-site disturbance and possible fill-related ground modification are visible.	

Recommendation

A current on-site water feature is present and should be considered in geotechnical assessment. Detailed geotechnical investigation is strongly recommended.

Current Site Image

North-up current imagery with the submitted lot boundary shown for site reference.

Source: mapbox_bbox_site

Geotechnical Risk Summary

The following preliminary risk commentary is based on interpreted site history features identified from available aerial imagery.

Disturbance / Fill Risk

ELEVATED

Visible disturbance within the site suggests that ground modification or placement of fill materials may have occurred. The origin and composition of such materials are typically unknown at this stage and may include uncontrolled fill. This can result in variable strength, moisture conditions, and overall soil behaviour, which may impact foundation performance and footing type, and contribute to differential settlement if not properly assessed in accordance with AS2870.

Pond / Wet Area Risk

HIGH

The presence of a current pond or pond-like depression within the site indicates localised moisture influence and potential variability in subsurface conditions. Such features are commonly associated with elevated moisture contents, soft or compressible soils, and conditions that may contribute to ground movement. These areas may remain seasonally wet or act as surface water collection points, which can impact foundation performance and are relevant to site classification considerations in accordance with AS2870.

Historical Evidence

Best historical image showing the clearest former water feature evidence. Annotation boxes have been removed for cleaner presentation.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | 1995-06-18

Later Comparison Image

Later imagery used to check whether the historical water feature remains visible or appears altered.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | 2021-07-17

Limitations & Disclaimer

Limitations

- Image resolution limits detection of small or subtle features.
- No subsurface data for fill or soil conditions.
- Vegetation may obscure smaller water or disturbance features.
- historical image resolution limits precise delineation
- some features obscured by vegetation
- Imagery resolution limits subtle feature clarity.

Disclaimer

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.