AI SITE HISTORY REPORT (Beta)

Address	502 Church Road, Taigum QLD
Generated	17 Apr 2026
Lot size	11,925 m^2
Years scanned	1995, 2005, 2011, 2015, 2019, 2021
Confidence	High

Preliminary Screening Notice

This report is generated using automated interpretation of available aerial imagery and is intended for preliminary site screening purposes only.

While reasonable effort has been made to identify visible indicators such as ponds, historical water features, and site disturbance, not all features may be detected or accurately interpreted.

Users are strongly encouraged to independently review historical imagery (e.g. Google Earth) and obtain a detailed geotechnical investigation in accordance with AS2870 prior to design, construction, or purchase decisions.

Current Site Overview

Figure 1: Current site overview used for automated screening.

Executive Summary

A current pond is present on-site. Historical imagery also indicates at least one additional former or altered pond / wet depression on-site. Site disturbance or possible fill-related ground modification is also visible. Adjacent off-site water features were identified and treated as contextual only.

Key Site Risks

Current Pond / Wet Area	High
A current pond or pond-like depression is present on-site and should be treated as a relevant moisture-related geotechnical risk.	
Former Water Features	High
Historical imagery indicates at least one additional former pond or altered wet depression on-site, separate from the current pond.	
Fill / Disturbance	Elevated
Existing building / hardstand footprints and associated on-site disturbance are visible, indicating prior localised ground modification.	

Recommendation

A current pond is present on-site and historical imagery also indicates at least one additional former or altered pond / wet depression. Detailed geotechnical investigation is strongly recommended.

Current Site Image

North-up current imagery with the submitted lot boundary shown for site reference.

Source: mapbox_bbox_site

Geotechnical Risk Summary

The following preliminary risk commentary is based on interpreted site history features identified from available aerial imagery.

Disturbance / Fill Risk

ELEVATED

Existing building / hardstand footprints and associated site disturbance indicate prior localised ground modification may have occurred. These areas can be associated with regrading, hardstand construction, service installation, slab preparation, or localised fill placement. The origin and composition of any modified ground remain unknown at this stage and may contribute to variable near-surface conditions, foundation performance issues, or differential settlement if not properly assessed in accordance with AS2870.

Historical Pond / Fill Risk

HIGH

Historical imagery indicates the presence of former water features or wet depressions within the site. These areas may have been infilled over time, potentially with uncontrolled or undocumented materials. Infilled pond zones can present significant geotechnical risks, including compressible soils, variable founding conditions, and potential for differential movement. The nature and extent of any fill materials should be confirmed through detailed geotechnical investigation in accordance with AS2870 requirements.

Pond / Wet Area Risk

HIGH

The presence of a current pond or pond-like depression within the site indicates localised moisture influence and potential variability in subsurface conditions. Such features are commonly associated with elevated moisture contents, soft or compressible soils, and conditions that may contribute to ground movement. These areas may remain seasonally wet or act as surface water collection points, which can impact foundation performance and are relevant to site classification considerations in accordance with AS2870.

Historical Evidence

Best historical image showing the clearest former water feature evidence. Annotation boxes have been removed for cleaner presentation.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | 1995-06-18

Later Comparison Image

Later imagery used to check whether the historical water feature remains visible or appears altered.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | 2021-07-17

Limitations & Disclaimer

Limitations

- Imagery resolution limits detailed fill depth or subsurface extent assessment.
- Vegetation may obscure minor disturbance or smaller water features.
- Resolution limits detection of very small or deeply buried features
- Visual screen does not confirm subsurface conditions or fill extent
- Imagery spatial resolution limits detailed feature characterization
- Water presence inference dependent on surface visibility and seasonality

Disclaimer

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.