Dale Automation

Tool Check List for Services

Inspection Details

Report #: Dale Automation 2785
Location: South Africa
Inspection Date: 01-Oct-2026 07:48 AM
Inspector Name: William Ludick

Asset Details

Asset Category : Fleet Vehicle
Asset Name : Transporter Van 2
Asset # : MD87GJGP
Meter Reading: 41285 KM
Model/Year: Volkswagen Transporter T5 Pickup

CHAIN BLOCKS

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	2TON CHAIN BLOCK 001		✓	○	○	○
2	2TON CHAIN BLOCK 002		✓	○	○	○
3	2TON CHAIN BLOCK 003		✓	○	○	○


1. 2TON CHAIN BLOCK 001



2. 2TON CHAIN BLOCK 002



3. 2TON CHAIN BLOCK 003



CONSUMABLES

SN	Inspection Item	Note	Good	Repair	Replace	NA
4	RAGS		✓	○	○	○
5	CABLE TIES T50R (BLACK)		○	○	○	−
6	CABLE TIES T50L (BLACK)		○	○	○	−

SN	Inspection Item	Note	Readings		
7	KLING SPORE CUTTING DISKS 115MM	Need to refill	✓	1	(0-100)
8	KLINGSPOR SANDING DISK #36GRIT	Need to refill	✓	1	(0-100)
9	KLINGSPOR SANDING DISK #60GRIT	Need to refill	✓	1	(0-100)
10	KLINGSPOR GRINDING DISK 115MM	Need to refill	✓	1	(0-5)
11	KLINGSPOR POLISHING WHEEL (FINE)	Don't have	✓	1	(0-10)

12	KLINGSPOR POLISHING WHEEL (MEDIUM)		✓	0	(0-10)
13	HERSCHELL SILICONE PASTE		✓	0	(0-5)
14	DEN BRAVEN SEALER (GREY)		✓	0	(0-50)
15	DEN BRAVEN SEALER (WHITE)	Have 2 full tubs	✓	2	(0-50)
16	PERFORMANCE FLUID PENETRATING SPRAY		✓	0	(0-5)
17	PERFORMANCE FLUID ELECTRICAL SPRAY		✓	0	(0-5)
18	PERFORMANCE FLUID XP-FG GREASE		✓	0	(0-10)
19	Q20 PENETRATING SPRAY	2 full cans	✓	2	(0-5)
20	EMERY CLOTH		✓	0	(0-20)
21	SCOTCH BRITE PADS	1 box almost empty	✓	1	(0-5)
22	INSULATION TAPE (BLACK)		✓	0	(0-4)
23	WURTH HAND SOAP	Half a tub		1	
24	S/S TIG FILLER WIRE 1,6MM	Still full		1	
25	S/S TIG FILLER WIRE 2,4MM	Still full		1	
26	MILD STEEL TIG FILLER WIRE 1,6MM			0	
27	MILD STEEL TIG FILLER WIRE 2,4MM			0	

12. DEN BRAVEN SEALER (WHITE)



16. Q20 PENETRATING SPRAY




CORDED POWER TOOLS

SN	Inspection Item	Note	Good	Repair	Replace	NA
28	115mm GRINDER (DEWALT)	Dewalt grinder Still good just needs spindle nuts ,have a corded makita grinder aswell but shocks durning grinding	○	✕	○	○
29	750W HAND DRILL (DEWALT)	Makita box still in van but drill is missing	○	○	✕	○
30	NUT RUNNER 350NM (BRAND)		○	○	○	−

28. 115mm GRINDER (DEWALT)





29. 750W HAND DRILL (DEWALT)



CORDLESS POWER TOOLS

SN	Inspection Item	Note	Good	Repair	Replace	NA
31	HAND DRILL (DEWALT)	Makita box present but drill missing from van	○	○	✕	○
32	NUT RUNNER 250NM (BRAND)	Still works perfectly	✓	○	○	○
33	NUT RUNNER 350NM (BRAND)	Still works perfectly	✓	○	○	○

31. HAND DRILL (DEWALT)



DRILL BITS

SN	Inspection Item	Note	Readings		
34	5MM DOUBLE SIDED	Need to replace	✓	0	(0-50)
35	DRILL BIT SET	Only old sharpened bits		0	

ELECTRICAL TOOLS

SN	Inspection Item	Note	Good	Repair	Replace	NA

36	CLAMP MULTIMETER	Don't have one in the van	○	○	○	⊖
37	STANDARD MULTIMETER	Don't have one in the van	○	○	○	⊖
38	INSULATED LUG CRIMPER	Don't have one in the van	○	○	○	⊖
39	BOOT LACE CRIMPER	Don't have one in the van	○	○	○	⊖
40	LUG & BOOT LACE BOX	Don't have one in the van	○	○	○	⊖
41	EXTENTION CORD TAG #		✓	○	○	○
42	EXTENTION CORD TAG #		✓	○	○	○

FIRE EXTINGUISHERS

SN	Inspection Item	Note	Good	Repair	Replace	NA
43	FIRE BLANKETS	Don't have one in the van	○	○	○	⊖

SN	Inspection Item	Note	Readings
44	4KG FIRE EXTINGUISHERS	Have 2 that are still good	2

43. 4KG FIRE EXTINGUISHERS





FIRST AID

SN	Inspection Item	Note	Good	Repair	Replace	NA
45	FIRST AID BOX		✓	○	○	○

GEARBOX TOOL BOX


SN	Inspection Item	Note	Good	Repair	Replace	NA
46	PIPE WRENCH ###MM	Van doesn't have one	○	○	○	⊖
47	PIPE WRENCH ###MM	Van doesn't have one	○	○	○	⊖
48	BREAKER BAR (GEDORE)	Van doesn't have one	○	○	○	⊖

49	46MM SPANNERS	Van doesn't have one	○	○	○	⊖
50	30MM SPANNERS	Have 2	✓	○	○	○
51	24MM SPANNERS	One have 1	○	○	○	⊖

KING TONY BOX 1

SN	Inspection Item	Note	Good	Repair	Replace	NA
52	DRAW 1	Missing 13 mm tube socket Missing punches	○	✕	○	○
53	DRAW 2	Missing 400G plastic rubber hammer Missing 8 inch long nose plier Missing 6 inch side cutter	○	○	✕	○
54	DRAW 3	Missing flat 8x200 Missing flat 6.5x150 Missing flat 3x100 Missing 1.5 mm flat	○	○	✕	○
55	DRAW 4	Missing t handel 3.0x100mm Missing hex allen key set	○	○	✕	○
56	DRAW 5	1/2" 1x 13 mm socket 1/2" 10" extention bar 27 and 32 mm sockets 1/4 x4" extention 1/4 x 2" extention 3/8" ratchet 1/4" rachet 1/4" spinner handle	○	○	✕	○
57	DRAW 6	Missing spanner sizes in mm(7,8,10,13,17,19 22) Missing 12x13mm spanner	○	○	✕	○
58	DRAW 7		✓	○	○	○

52. DRAW 1




53. DRAW 2




54. DRAW 3




55. DRAW 4



56. DRAW 5



57. DRAW 6



58. DRAW 7



KING TONY BOX 2

SN	Inspection Item	Note	Good	Repair	Replace	NA
59	DRAW 1	Missing flat steel file 16x175 chisel 11x 145mm chisel 3x125,4x125,6x150,4x150 punches	○	✕	○	○
60	DRAW 2		✓	○	○	○
61	DRAW 3	400g rubber hammer missing 300g hammer 8" pliers 6"side cutter 10" locking piers Straight nose internal circlip pliers	○	○	✕	○
62	DRAW 4	Missing flat 6x150,6x100,3x75 Ph 000	○	○	✕	○
63	DRAW 5	Missing 17mm socket 13mm for 3/8" socket 1/4" x2" extention 8mm 1/4" socket 1/4" spinner handel 1/4" ratchet	○	✕	○	○
64	DRAW 6	Missing spanners 7mm ,10mm,12mm,19mm Missing combination 6x7mm	○	○	✕	○
65	DRAW 7	Missing 8mm tube spanner	○	○	✕	○

59. DRAW 1




60. DRAW 2



61. DRAW 3



62. DRAW 4




63. DRAW 5



64. DRAW 6



65. DRAW 7



SLINGS & STRAPS

SN	Inspection Item	Note	Pass	Fail	NA
66	SLING TAG #101		✓	○	○
67	SLING TAG #102		✓	○	○
68	SLING TAG #103		✓	○	○
69	SLING TAG #104		✓	○	○
70	SLING TAG #105		✓	○	○
71	SLING TAG #106		✓	○	○
72	SLING TAG #107		✓	○	○
73	SLING TAG #108		✓	○	○
74	SLING TAG #109		✓	○	○
75	SLING TAG #110		✓	○	○
76	SLING TAG #111		✓	○	○
77	SLING TAG #112		✓	○	○
78	SLING TAG #113		✓	○	○
79	SLING TAG #114		✓	○	○
80	SLING TAG #115		✓	○	○
81	SLING TAG #116		✓	○	○
82	SLING TAG #117		✓	○	○
83	SLING TAG #118		✓	○	○
84	SLING TAG #119		✓	○	○
85	SLING TAG #120		✓	○	○
86	SLING TAG #121		✓	○	○

SPECIALTY TOOLS

SN	Inspection Item	Note	Good	Repair	Replace	NA
87	KING TONY TORQUE WRENCH		✓	○	○	○
88	STANLEY 5M TAPE MEASURE	Van doesn't have one	○	○	○	−
89	STANLEY 10M TAPE MEASURE	Van doesn't have one	○	○	○	−
90	150MM VERNIER CALIPER	Van doesn't have one	○	○	○	−
91	BEARING PULLER ###MM		✓	○	○	○
92	MANUAL OIL PUMP		○	○	○	−

WELDING MACHINE AND HELMET

SN	Inspection Item	Note	Good	Repair	Replace	NA
93	HELMET	Helmet works but is cracked	○	✕	○	○
94	WELDING TORCH		✓	○	○	○
95	WELDING MACHINE #101	Has been given in for repairs	○	○	○	−

SN	Inspection Item	Note	Readings	
96	TUNGSTENS 2.4MM RED TIP		✓ 0	(0-20)
97	COLLETS 2,4MM		✓ 0	(0-5)
98	COLLET BODY		✓ 0	(0-5)
99	CERAMIC CUP #5		✓ 0	(0-5)
100	CERAMIC CUP #8		✓ 0	(0-5)
101	BACKING CAP (SHORT)		✓ 0	(0-5)
102	BACKING CAP (LONG)		✓ 0	(0-5)

93. HELMET





Additional Note
Needs a lot of tools

Overall Condition:	Major Repair required
Asset Safe to Use:	**Yes**
Maintenance Required:	Yes
Asset Status	Maintenance Required
Maintenance Priority:	Medium

Custom Business Fields

Client Name : Dale

Contact details : 0834386516



_____

Dale Technician Signature



_____

Client Signature