Summit Hood Services

Kitchen exhaust cleaning service record

Record HC-20261019-A1B2
Service date: Oct 19, 2026
Technician: Maria Lopez

Next cleaning due: Jan 19, 2027

Harbor Grill

412 Dock St, Portland, OR 97204

Areas serviced


Hood	**Pass**
Filters	**Pass**
Ductwork	**Pass**
Fan	**Deficiency**
Note: Belt wear noted, fan cleaned and operational.	
Access panels	**No access**
Reason: Panel sealed, documented no access	
Grease containment	**Pass**
Fire-suppression nozzles visible/unobstructed	**Pass**

Photo documentation

Sample photos, not from a real job. Cropped and Compressed. For web.


Filters

Before
Oct 19, 10:05 AM



"Long-uncleaned kitchen hood filter, close-up"
by Veikk0.ma, CC BY-SA 4.0
Wikimedia Commons

After
Oct 19, 11:40 AM



"Kitchen hood filter after being washed in a dishwasher, close-up"
by Veikk0.ma, CC BY-SA 4.0
Wikimedia Commons

Serviced by Maria Lopez, Summit Hood Services

This document is a service record from your kitchen exhaust cleaning company. It is not a fire inspection, code compliance certification, or NFPA compliance certificate. Cleaning frequency guidance references NFPA 96 cooking-volume schedules. The authority having jurisdiction and your insurer determine what documentation they accept.