# Summit Hood Services

Kitchen exhaust cleaning service record

Record HC-20261019-A1B2
Service date: Oct 19, 2026
Technician: Maria Lopez

# Next cleaning due: Jan 19, 2027

## Harbor Grill

412 Dock St, Portland, OR 97204

### Areas serviced


| | |
|---|---|
| Hood | **Pass** |
| Filters | **Pass** |
| Ductwork | **Pass** |
| Fan | **Deficiency** |
| Note: Belt wear noted, fan cleaned and operational. | |
| Access panels | **No access** |
| Reason: Panel sealed, documented no access | |
| Grease containment | **Pass** |
| Fire-suppression nozzles visible/unobstructed | **Pass** |

### Photo documentation

*Sample photos, not from a real job.*


**Filters**

**Before**
**Oct 19, 10:05 AM**



"Long-uncleaned kitchen hood filter, close-up"
by Veikk0.ma, CC BY-SA 4.0
Wikimedia Commons

After
Oct 19, 11:40 AM



"Kitchen hood filter after being washed in a dishwasher, close-up"
by Veikk0.ma, CC BY-SA 4.0
Wikimedia Commons

### Serviced by Maria Lopez, Summit Hood Services

This document is a service record from your kitchen exhaust cleaning company. It is not a fire inspection, code compliance certification, or NFPA compliance certificate. Cleaning frequency guidance references NFPA 96 cooking-volume schedules. The authority having jurisdiction and your insurer determine what documentation they accept.