INCIDENT TYPE: Infrastructure / Road Blockage

DATE: April 22, 2026

1. LOCATION DETAILS Location: Main Entrance (Gate No. 1), IIT Patna

Address: Bihta-Kanpa Road, Bihta, Patna, Bihar 801103.

Landmark: Near the Security Checkpost / Main Archway.

2. INCIDENT DESCRIPTION Issue: Due to sudden severe weather and high winds, a large Banyan tree has uprooted and fallen directly across the main entry road.

Impact: The road is partially blocked, creating a significant traffic hazard for buses and faculty vehicles entering the campus. Immediate assistance is needed to divert traffic and ensure the safety of pedestrians near the gate until the heavy machinery arrives to remove the debris.

3. URGENCY ASSESSMENT Urgency Level: 8 / 10

Priority Status: HIGH Reasoning: Road blockage at a major educational institution. Risk of vehicular accidents in low visibility conditions.

4. VOLUNTEER REQUEST Number of Volunteers Needed: 2

Task Description: * Coordinate traffic flow at the gate.

- Set up temporary caution tape/barriers.
- Guide students away from the fallen branches.

REPORTED BY: Campus Security Office