

KMRL Safety Inspection Report – Corridor 2

Category: Inspection Report (safety, quality, or routine)

Date: 18-08-2026

The safety inspection of Corridor 2 (Edappally – Tripunithura) was conducted on 17-Aug-2026. All signaling systems are operational. However, the level crossing at Maradu needs immediate attention due to worn-out gates. No critical anomalies were detected. The team recommends a follow-up inspection next month.

Action Items:

- Replace level crossing gates at Maradu
- Schedule follow-up inspection for September

Deadline: 2026-09-10